



PCB-Hole pattern

No. of contacts	A ±0,2	B ±0,1	C1 ±0,1	C2 ±0,1	D ±0,1
13	45,6	12 x 2,5 = 30	12 x 2,5 = 30	12 x 2,54 = 30,48	40
21	65,6	20 x 2,5 = 50	20 x 2,5 = 50	20 x 2,54 = 50,80	60
31	90,6	30 x 2,5 = 75	30 x 2,5 = 75	30 x 2,54 = 76,20	85